

Jumpers (1 = Solder)		
Label	76543210	ROMident
[unused]	00000000	[unused]
19XA	00000001	19xxa
19XB	00000010	19xxb
19XH	00000100	19xxh
19XJ	00000101	19xxj
19XU	00000110	19xx
AVPA	00000111	avspa
AVPE	00001001	avsp
AVPH	00001010	avsph
AVPJ	00001011	avspj
AVPU	00001100	avspu
BTCA	00001101	batcira
BTCE	00001111	batcir
BTCJ	00010001	batcirj
CSCA	00010011	cscluba
CSCE	00010101	csclub
CSCH	00010110	csclubh
CSCJ	00010111	csclubj, csclubjy
CYBE	00011011	cybots
CYBJ	00011101	cybotsj
CYBU	00011110	cybotsu
DADA	00011111	ddtoda
DADE	00100001	ddtod
DADH	00100010	ddtodh
DADJ	00100011	ddtodj
DADU	00100100	ddtodu
DD2A	00100101	ddsoma
DD2B	00100110	ddsomb
DD2E	00100111	ddsom
DD2H	00101000	ddsomh
DD2J	00101001	ddsomj
DD2U	00101010	ddsomu
GGWA	00101011	gigawinga
GGWB	00101100	gigawingb
GGWH	00101110	gigawingh
GGWJ	00101111	gigawingj
GGWU	00110000	gigawing
GMDE	00110011	dimahoo
GMDJ	00110101	gmahou
GMDU	00110110	dimahoou
HS2A	00110111	hsf2a
HS2J	00111011	hsf2j
HS2U	00111100	hsf2

Jumpers (1 = Solder)		
Label	76543210	ROMident
MAJJ	00111101	jyangoku
MMXJ	01000010	mmatrixj
MMXU	01000011	mmatrix
MPN_	01000100	mpang, mpangj, mpangu
MSHA	01000101	msha
MSHB	01000110	mshb
MSHE	01000111	msh
MSHH	01001000	mshh
MSHJ	01001001	mshj
MSHU	01001010	mshu
MVCA	01001011	mvsc
MVCB	01001100	mvscb
MVCE	01001101	mvsc
MVCH	01001110	mvsch
MVCJ	01001111	mvscj, mvscjsing
MVCU	01010000	mvscu
MVSA	01010001	mshvsfa
MVSB	01010010	mshvsfb
MVSE	01010011	mshvsf
MVSH	01010100	mshvsfh
MVSJ	01010101	mshvsfj
MVSU	01010110	mshvsfu
NFFJ	01011011	1944j
NFFU	01011100	1944
PCFA	01011101	sgemfa
PCFH	01100000	sgemfh
PCFJ	01100001	pfghtj
PCFU	01100010	sgemf
PGAA	01100011	progeara
PGAJ	01100111	progearj
PGAU	01101000	progear
PL2_	01101001	pzloop2, pzloop2j
PWGA	01101010	armwara
PWGE	01101100	armwar
PWGJ	01101110	pgear
PWGU	01101111	armwaru
PZFA	01110000	spf2a
PZFE	01110010	spf2t
PZFH	01110011	spf2th
PZFJ	01110100	spf2xj
PZFU	01110101	spf2tu
RCMJ	01111010	rmancp2j
RCMU	01111011	mmancp2u

Jumpers (1 = Solder) 76543210		
Label	76543210	ROMident
RM2A	01111100	megaman2a
RM2H	01111111	megaman2h
RM2J	10000000	rockman2j
RM2U	10000001	megaman2
SFXA	10000010	ssf2ta
SFXE	10000100	ssf2t
SFXH	10000101	ssf2th
SFXJ	10000110	ssf2xj
SFXO	10000111	ssf2xjr1r
SFXU	10001000	ssf2tu
SFZA	10001001	sfza
SFZB	10001010	sfzb
SFZE	10001011	sfa, sfar1, sfar2, sfar3
SFZH	10001100	sfzh
SFZJ	10001101	sfzj
SFZU	10001110	sfau
SMBA	10001111	ringdesta
SMBE	10010001	ringdest
SMBH	10010010	ringdesth
SMBJ	10010011	smbomb
SSFA	10010101	ssf2a
SSFA_T	10010110	ssf2tba
SSFE	10011001	ssf2
SSFE_T	10011010	ssf2tb
SSFH	10011011	ssf2h
SSFH_T	10011100	ssf2tbh
SSFJ	10011101	ssf2j
SSFJ_T	10011110	ssf2tbj
SSFU	10011111	ssf2u
SSFU_T	10100000	ssf2tbu
SZ2A	10100001	sfz2a
SZ2B	10100010	sfz2b
SZ2E	10100011	sfa2
SZ2H	10100100	sfz2h
SZ2J	10100101	sfz2j
SZ2N	10100110	sfz2n
SZ2U	10100111	sfa2u
SZ3A	10101000	sfz3a
SZ3B	10101001	sfa3b
SZ3E	10101010	sfa3
SZ3H	10101011	sfa3h
SZ3J	10101100	sfz3j
SZ3U	10101101	sfa3u

Jumpers (1 = Solder) 76543210		
Label	76543210	ROMident
SZAA	10101110	sfz2al
SZAB	10101111	sfz2alb
SZAH	10110001	sfz2alh
SZAJ	10110010	sfz2alj
TKOJ	10110100	choko
TQZJ	10110101	qndream
UECA	10110110	ecofghtra
UECE	10111000	ecofghtr
UECH	10111001	ecofghtrh
UECJ	10111010	uecology
UECU	10111011	ecofghtru
VAMA	10111100	dstlka
VAME	10111110	dstlk
VAMH	10111111	dstlkh
VAMJ	11000000	vampj, vampja
VAMU	11000001	dstlku
VH2J	11000010	vhunt2
VM3A	11000011	vsava
VM3E	11000101	vsav
VM3H	11000110	vsavh
VM3J	11000111	vsavj
VM3U	11001000	vsavu
VPHA	11001001	nwarra
VPHB	11001010	nwarrb
VPHE	11001011	nwarr
VPHH	11001100	nwarrrh
VPHJ	11001101	vhuntj
VPHU	11001110	nwarrru
VS2J	11001111	vsav2
XMNA	11010000	xmcotaa
XMNB	11010001	xmcotab
XMNE	11010010	xmcota
XMNH	11010011	xmcotah
XMNJ	11010100	xmcotaj
XMNU	11010101	xmcotau
XVSA	11010110	xmvsfa
XVSB	11010111	xmvsfb
XVSE	11011000	xmvsf
XVSH	11011001	xmvsfh
XVSJ	11011010	xmvsfj
XVSU	11011011	Xmvsfu